

**Town Of Addison, Texas**  
**Closes: July 9, 2024 Beginning at 12:00 PM CDT**  
[Go to Auction Details](#)

[<< Auction Details](#)

Hide ended lots







1 2 | [Last 12](#)

Category: All (32)






ALL LOTS (32) ▼

Lot	Photo	Description	Bids	High Bidder	Current Amount	Next Bid Req	Your Bid	Your Max
<a href="#">219</a>		<p>2016 Dodge 4500HD Frazer Ambulance; VIN [REDACTED]; 70,701 Miles; 6,125 Hours; 6.7L Diesel; Starts with boost; Logos removed; A/C; PS; PB; PL; PW; Radio; Last utilized 1/23; The photographs of this vehicle show emergency lights and equipment however, if the winning bidder is not a police agency, fire department, emergency medical service organization or an ambulance service agency, all lights and emergency equipment will be removed prior to vehicle delivery to the bidder. If a reseller of emergency apparatus purchases the vehicle, all emergency lights and equipment will be removed; Location 1</p> <p>AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Miles and Hours are not guaranteed; Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.</p>	25	103542	38000.00	38100.00		<i>Lot has ended</i>
<a href="#">740</a>		<p>1999 GMC Isuzu W4 Vactor Boss Pipe Hunter Sewer Truck; VIN [REDACTED]; 13,373 Miles; 4.75L L4 Diesel; Auto; Bucket seats; Rubber mats; Starts with boost; A/C; PS; PB; Radio; Location 1</p> <p>AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Miles and Hours are not guaranteed; Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.</p>	13	26000	8600.00	8650.00		<i>Lot has ended</i>
<a href="#">718</a>		<p>2015 Ford F350 Extended Cab Pickup; VIN [REDACTED]; 49,128 Miles; 6.2L V8 Gas; Auto; 60-40 seats; Starts with boost; Runs/Is drivable; Logo residue; A/C; PS; PB; PL; PW; Rdio; Last utilized 4/24; Location 1</p> <p>AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Miles and Hours are not guaranteed; Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.</p>	35	84671	16600.00	16700.00		<i>Lot has ended</i>
<a href="#">719</a>		<p>2015 Ford F150 Extended Cab Pickup; VIN [REDACTED]; 67,914 Miles; 3.5L V6 Gas; Auto; Bucket seats; Rubber mats; Starts; Logo residue; A/C; PS; PB; PL; PW; Cruise control Radio; Equipped with Public Works lightbar; Location 1</p>	17	14997	13308.00	13408.00		<i>Lot has ended</i>

AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Miles and Hours are not guaranteed; Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

<a href="#"><u>1</u></a>		Animal Control Body; Location 1	<a href="#"><u>5</u></a>	50565	145.01	155.01	Lot has ended
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#"><u>2</u></a>		Target Pro35II Concrete Saw; Diesel; Location 1	<a href="#"><u>14</u></a>	69266	825.00	875.00	Lot has ended
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#"><u>3</u></a>		Bluebird Easyscape Aerator; Location 1	<a href="#"><u>23</u></a>	88297	700.00	750.00	Lot has ended
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#"><u>M1</u></a>		Concrete Planter set of 3 sold as set - heavy; Location 2	<a href="#"><u>7</u></a>	82880	160.00	170.00	Lot has ended
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#"><u>M2</u></a>		Black soft sofa - 6 foot; Location 2	<a href="#"><u>8</u></a>	21921	105.00	115.00	Lot has ended
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#"><u>M3</u></a>		Black sofa; Location 2	<a href="#"><u>6</u></a>	21921	92.00	102.00	Lot has ended
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text					

description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

<a href="#">M4</a>		One Black love seat - same photos used for lots M4 and M5 - will be distributed on a first come, first pick basis; Location 2	<a href="#">8</a>	21921	115.00	125.00	<i>Lot has ended</i>
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#">M5</a>		One Black love seat - same photos used for lots M4 and M5 - will be distributed on a first come, first pick basis; Location 2	<a href="#">7</a>	21921	105.00	115.00	<i>Lot has ended</i>
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#">M6</a>		Black couch and love seat set; Location 2	<a href="#">12</a>	21921	230.00	240.00	<i>Lot has ended</i>
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#">M7</a>		One Blue wing back chair - same photo used for lots M7 and M8 - will be distributed on a first come, first pick basis; Location 2				5.00	<i>Lot has ended</i>
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#">M8</a>		One Blue wing back chair - same photo used for lots M7 and M8 - will be distributed on a first come, first pick basis; Location 2				5.00	<i>Lot has ended</i>
		AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.					
<a href="#">M9</a>		One Orange Chair - same photos used for lots M9 through M11 - will be distributed on a first come, first pick basis; Location 2	<a href="#">1</a>	71043	5.00	10.00	<i>Lot has ended</i>



AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

M10



One Orange Chair - same photos used for lots M9 through M11 - will be distributed on a first come, first pick basis; Location 2

1

71043

5.00

10.00

*Lot has ended*

AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

M11



One Orange Chair - same photos used for lots M9 through M11 - will be distributed on a first come, first pick basis; Location 2

1

71043

5.00

10.00

*Lot has ended*

AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

M12



2 ft x 4 ft x 6 ft shelving unit; Location 2

5

20680

35.00

45.00

*Lot has ended*

AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

M13



One 5 ft x 30 in stainless table on castors; Location 2

7

10449

171.00

181.00

*Lot has ended*

AS-IS; Current condition UNKNOWN. This item is used and may contain defects that are not immediately detectable. Text description given is meant to be used as a guide only. You are responsible for inspecting item before bidding. All information provided is believed to be correct but no warranty as such is either intended or implied. All items are sold AS IS - WHERE IS AND WITH ALL FAULTS AND DEFECTS THEREIN.

A decimal point (.) is required in all bids. Do NOT use a comma when bidding.



**Submit bids**

**Review bids**

**Increments**

[<< Auction Details](#)

1 2 | [Last 12](#)